



551236

Post Site Inspection

Site Name: Comerco Inc Olympic Stain Div I.D. Number ILD085224186
Date of Inspection: 2/7/89

Was Work Plan Followed

Y

N

If no, explain briefly:

Work plan called for 3 residential well samples. No res. wells were found in the vicinity of the site so none were sampled. Work plan called for 11 soil/sediment samples to be collected. Only 7 were collected due to much gravel and concrete present at site which limited possible sampling locations.

Were Samples Collected?

Y

N

Residential Wells Sampled?

Y

N

Anticipated Analysis Report From:

CRL _____

CLP _____

Anticipated SILENCE Completion: 7/89

Removal Investigation Recommended

Y

N

If yes, explain briefly:

Unanticipated Problems Encountered

Y

N

If yes, explain briefly:

very cold!

Follow-up site work necessary

Y

N

If yes, explain briefly:

none apparent